

# LP7650

## Heavy Duty Crane Scale



### Upgrade Function:

- Tare Set
- Total/Delete/Clear total/View total weight
- Resolution switch
- Auto power-off set
- Display luminance set
- Anti-motion set

### Basic Function:

- Zero/Tare/Hold/Total
- Low voltage alarm
- Battery supervision
- Overload alarm
- Kg/lb conversion
- Gravity acceleration set



### Feature: //

- Die-casting aluminum enclosure, sand -blasting and powered coated. Anti-corrosion
- Sealing design, Moisture proof
- Alloy steel shackle to protect from overload.
- High capacity rechargeable battery
- Water-proof keypads
- Infrared remote control
- Capacity: 1000/2000/3000/5000/10000kg

### Specifications: //

- 38mm LED or 30mm LCD display
- Accuracy Class: OIML III
- Tare Range: 100% F.S
- Zero Range: 2% F.S
- Safe Overload: 130% F.S
- Ultimate Overload: 400% F.S
- Overload Alarm: 100%F.S+9e
- Battery: 6V 4.5Ah
- Battery life: >80h
- Temperature range: -10°C ~40°C
- Adapter: 9V 1200mA

### Configuration Table: //

Item	Model	Max. Cap(t)	Div(kg)	Size:W*L*H(mm)	Weight(kg)
LP7650-1	OCS-A1-1	1	0.5/0.2	242*290*458	9.8
LP7650-2	OCS-A1-2	2	1/0.5	242*290*458	9.8
LP7650-3	OCS-A1-3	3	1/0.5	242*290*458	9.8
LP7650-5	OCS-A1-5	5	2/1	242*290*564	14
LP7650-10	OCS-A1-10	10	5/2	242*290*768	32