

# LP7512

## Weighing Indicator

### FEATURES & BENEFITS:

- 6 digits 0.8" LED or LCD display with backlight
- Stainless steel or mild steel Enclosure
- Key: On/off Total Tare Zero Set
- Drives up to four 350Ω load cells
- Automatic Power off
- Low-battery remind



### Options: //

- RS-232 Serial Port
- built-in printer

### Specifications: //

- Accuracy Class:  $\text{III}$ ,  $n=3000e$
- A/D converting speed: 10 times/sec
- Input single range: 0~19.5mv
- Excitation circuit: 5 VDC, 4 wire connection  
4 load cell of 350Ω
- Max division: 15,000d
- Power: 6V/4Ah rechargeable battery or 9VDC adapter
- Operation temperature: -10~40°C
- Operation humidity: ≤85%RH

• Unit: mm

